

Table of Contents

Chapter 1

Design of Experiment Process	1
Introduction.....	2
Basic Approach.....	2
Design of Experiment Definition.....	3
Why Use the Design of Experiment Process?	3
Design of Experiment Limitations.....	4

Chapter 2

Getting Started - Identify the Key Input Factors	5
Input Factor Universe	6
Power Supply Technology	6
Power Supply Technology Classification.....	6
Stored Energy (Capacitive Discharge)	6
Direct Energy (AC)	6
Inverter.....	7
Liner DC	7
Power Supply Parameters	7
Weld Head Technology	8
Weld Head Issues.....	8
Manual Weld Head Technology	8
Air Actuated Weld Head Technology, No Over-force Protection.....	9
Actuated Weld Head Technology, With Over-force Protection.....	9
Servo-Driven Weld Head Technology.....	9
Magnetic-Driven Weld Head Technology.....	9
Weld Head Parameters.....	10
Electrode Parameters	10
Material Parameters	12
Material Geometry Factors	12

Chapter 3

Reduce the Number of Input Variables	14
Life is Too Complex	15
The Reduction Process.....	15
Opposed Weld Example	15
Parallel Gap Weld Example.....	17

Chapter 4

Identify the Key Output Responses	18
Output Response Universe.....	19
Weld Quality Definition	19
Quantifiable Output Response Measurements.....	20
Qualitative Output Responses.....	20

Chapter 5

Find the “Corners of the Box” 22

- Resistance Welding Box 23
- Move the Box..... 23
- DoE Software Capability 23
- Find the Minimum “Corner” – Opposed Weld Example..... 24
 - Opposed Weld Input Factors 24
 - Weld Force Magnitude – Minimum Weld Heat 24
 - Minimum Weld Heat Combination 24
 - Getting Started 25
- Find the Maximum “Corner” – Opposed Weld Example..... 26
 - Weld Force Magnitude – Maximum Weld Heat..... 26
 - Maximum Weld Heat Combination..... 26
 - Continuing to Experiment..... 26
- Find the Minimum “Corner” – Parallel Gap Weld Example 27
 - Parallel Gap Weld Input Factors..... 27
 - Electrode Gap – Minimum Weld Heat 27
 - Weld Force Magnitude – Minimum Weld Heat 28
 - Minimum Weld Heat Combination 28
 - Getting Started 28
- Find the Maximum “Corner” – Parallel Gap Weld Example 29
- Test the “Corners”..... 30

Chapter 6

Conduct the DoE 31

- DoE Software Selection 32
- DoE Model Selection..... 32
- Opposed Weld Example 33
- Parallel Gap Weld Example..... 35

Chapter 7

Analyze the DoE 38

- General Analysis Approach 39
- Prediction Models 39
- “Rules of Thumb” 40
 - Adjusted Coefficient of Determination (Adj Rsq)..... 40
 - P(2 Tail) 40
 - Coeff 41

Opposed Weld Example	42
Run the Multiple Regression	42
Check Y-hat and S-hat Model Validity	42
Revise the S-hat Model	43
Optimize the Prediction Model	44
Plot the Output Response	47
Perform the Confirmation Run	50
Analyze the Confirmation Run	50
Parallel Gap Weld Example	51
Run the Multiple Regression	51
Check Y-hat and S-hat Model Validity	51
Revise the S-hat Model	52
Optimize the Prediction Model	53
Plot the Output Response	54
Perform the Confirmation Run	58
Analyze the Confirmation Run	58
Summary	59
Glossary	60
Index	62